NoCAMY HOUSE 401 South Thornton Avenue Dalton Whitfield County Georgia HABS No. GA 2223

HARSS CA. 1677-DAIST

## PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey National Park Service Southeast Region Department of the Interior Atlanta, Georgia 30303

## UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE


HABS GA 157-DALT

5-2-89

## ARCHITECTURAL DATA FORM

				•	
ST	COUNTY			TOWN OR VICINITY	
GEORGIA	Whitfield		DALTON		
HISTORIC NAME OF STRUCTURE (INC.)	UDE SOURCE FOR	NAME)	14	HABS NO.	
McCAMY HOUSE				GA-2223	
SECONDARY OR COMMON NAMES OF S	STRUCTURE				
					Ξ.
COMPLETE ADDRESS (DESCRIBE LOCA	TION FOR RURAL	SITES)			
401 South Thornton Aver	iue				1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
DATE OF CONSTRUCTION (INCLUDE SO (Whitfield County Dec	OURCE)	ARCHITECT(S) (INC.	LUDE SOURCE)		
1907 Historic Pre. Comm.	Unknown				
SIGNIFICANCE (ARCHITECTURAL AND	HISTORICAL, INC	LUDE ORIGINAL USE	OF STRUCTURE)		
The house was used as a residence until vacated in 1988. The Spanish					
mission style was uncharacteristic of the neighborhood and City of Dalton.					
	<del></del>				
STYLE <i>(IF APPROPRIATE)</i> Spanish Colonial ''Missi	Lon''				
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)					
Stucco on wood bearing b	rick and woo	od stud framin	g.		
SHAPE AND DIMENSIONS OF STRUCTU	IRE (SKETCHED FL	OOR PLANS ON SEPAI	RATE PAGES ARE A	CCEPTABLE)	
<b>e</b> tached	•				
EXTERIOR FEATURES OF NOTE Hear	vy arched openi	ings with a multi	-height parape	t above	• _
EXTERIOR FEATURES OF NOTE Heavy arched openings with a multi-height parapet above surrounds the entry porch. An Hispanic pediment penetrates the roof line to add emphasis to the entry door which is centered on the pediment. Roof overhangs are emphasized					
by wooden brackets at each co	mer.			1	
INTERIOR SEATURES OF NOTE (DESC	RIRE EL OOR PLAN	S JE NOT SKETCHED)			
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) Partially open staircase from the foyer to the second floor. Two brick fireplaces in					
foyer and living room. Small fireplace with panelized wood treatment above and coffered ceiling in the dining room.					
correred certifig in the diffin	g room.			·	
MAJOR ALTERATIONS AND ADDITION The structure was acquired fr	SWITH DATES	Commu Estate in 19	988 by develope	ers proposir	าย
alteration to office use. The	interior was	extensively gutte	ed and sheetro	k was appli	ied
over walls and ceilings.					
PRESENT CONDITION AND USE		. 1 10	T	males datassi.	
The house has been unoccupied condition although some renov	. for approximation had begin	tety to months.	It is it extre	nery deterro	maren
OTHER INFORMATION AS APPROPRIA The house remained essentiall	y unchanged du	ring T.S. McCamy	's ownership.	After acqui Renovation	isition
in 1988 the structure was gut terminated when new bank obta	ted and renova-	tion for office;	space begun. i	Renovacion	
SOURCES OF INFORMATION (INCLUDI Interview with Mrs. Mary Gene	NG LISTING ON NA Dykes; Histor	<i>TIONAL REGISTER, S</i> ic Preservation	<i>TATEREGISTERS,</i> Commission of T	<i>FIC)</i> Salton reco	rds;
Inventory form - Georgia Arch	itectural and	Historic Propert	ies Survey		
COMPILER AFFILIATION		Dalton/Whitf	ield DAI	ΓF	

J. R. Bates, Jr. Attorney/Director Bank & Trust



FIRST FLOUR PLAN (NORTH NO SCALE 5.2.89

